

| # | DESCRIPTION | PART NUMBER | QUANTITY |
|-----|---|-------------|----------|
| 1. | Hour Meter - VDO* | KSPW0022 | 0 |
| 2. | Vertical Speed Indicator - Feet per Minute* | KSAV0008 | 0 |
| 3. | Altimeter* | KSAV0001 | 0 |
| 4. | Air Speed Indicator* | KSAV0017 | 0 |
| 5. | Battery/Ground Cable*** | ---- | 0 |
| 6. | Oil Pressure Gauge* | ---- | 0 |
| 7. | Oil Temperature Gauge - VDO** | KSPW0017 | 0 |
| 8. | RPM Gauge - VDO* | KSPW0028 | 0 |
| 9. | Cylinder Head Temperature Gauge - VDO* ** | KSPW0017 | 0 |
| 10. | Battery/Solenoid Cable*** | ---- | 0 |
| 11. | Solenoid/Starter Cable | KAES0003 | 1 |
| 12. | Starter/Ground Cable | KAES0007 | 1 |
| 13. | 12 Gauge Wire* | ---- | 0 |
| 14. | 5 Wire Bundle - 26 Gauge Wire | KSES0022 | 26 ft |
| 15. | 20 Gauge Wire* | ---- | 0 |
| 16. | Trim Position Indicator***** | ---- | 0 |
| 17. | Solenoid **** | ---- | 0 |
| 18. | Regulator/Rectifier **** | ---- | 0 |
| 19. | 14 Gauge Wire* | ---- | 0 |
| 20. | Outside Air Temperature Gauge Kit - VDO* | KSIP0009 | 0 |
| 21. | Voltmeter - VDO* | KSES0009 | 0 |
| 22. | Battery, 912*** | ---- | 0 |
| 23. | Ignition Switch | KSES0027 | 1 |
| 24. | 2 Plex - 20 Gauge Wire* | ---- | 0 |
| 25. | Master Switch* | ---- | 0 |
| 26. | 1/4" Bolt | AN4-10A | 1 |
| 27. | 1/4" Steel Shear Nut | AN364-428C | 1 |
| 28. | Capacitor - 22,000 microFarad / 25v * | ---- | 0 |
| 29. | Hour Meter Relay Assembly | KAES0016 | 1 |
| 30. | Relay Mount Bracket | KPES0025 | 1 |
| 31. | 1/8" Stainless Steel Rivet | CCPQ-41 | 2 |

*Optional or Builder supplied **Oil Temperature & CHT use the same type of gauge.

Referenced from 912 battery box installation. *Supplied with engine.

*****Reference Mac Servo Kit.